

Technical Data Sheet



Xtend W-4008

50 Cambridge Drive, Monroe, CT 06468

Phone: 718-672-83 Fax: 718-565-7447 E-mail: info@axelplastics.com

www.axelplastics.com

Product Description

Proprietary resin emulsion comprising modified polymers which crosslink and form a semi-permanent release film upon evaporation of the water carrier.

Composition

Aqueous emulsion of proprietary resins and crosslinkers with various surfactants.

Handling

Keep this water-based product from freezing and store below 100°F / 39°C. Mix/agitate well before using.

Features

Easy spray or wipe on No HAPS No odor

Uses

Specifically designed for **Rotational Molding** of polyethylene and polypropylene up to 1000°F/537°C.

Typical Properties

Solids	8.0 – 10.0%
pН	6.0 - 8
Color	Off-white
Specific Gravity	1.00 @25°C
Viscosity	<15cps @25°C
Flash Point	Non Flammable
Shelf Life	12 months in original unopened package

Mold Preparation

XTEND W-4008 can be applied over the top of most other rotational molding release agents. This is recommended when the mold surface is in good condition and cleaning or stripping is not necessary for the quality of the molded part. However, for longest lasting results, it is recommended to remove previous release agents prior to application and curing of the W-4008. AXEL CX-200HS Mold Stripper can be used to remove previous release agents. If media blasting or abrading the surface mechanically, the mold should be thoroughly cleaned with Mineral Spirits, and then AXEL CX-500 Mold Cleaner or acetone prior to applying the AXEL XTEND XTEND W-4008 Mold Release.

Note: The most common problem when poor release results after mold cleaning, is blast media left in the tool due to improper cleaning.

Application Instructions

Dry-cycle/Dry bake for new or stripped/clean tools:

Use a cotton cloth or industrial paper shop towel. Soak the cloth with release until saturated and wipe onto the mold surface using smooth even strokes until the film is uniformly dry without wiping marks. It is NOT recommended to wipe on to a very warm or hot mold. The mold release may also be sprayed on to an ambient mold. Wiping on is strongly recommended the first time the XTEND W-4008 is applied, especially for cast aluminum tools or any tool with a textured surface. If spraying, any drips, runs, or over-spray should be wiped to ensure an even coating. Do not spray or mist on to very warm or hot molds unless quality spray equipment with proper atomization is used.

FULL CURE: Multiple coats (2-3) are recommended to achieve proper results/performance. The first coat should be applied and allow to dry to the touch. Then apply the second coat and, for maximum longevity, dry-cycle the mold through the oven and cooling cycle. Once the mold has cooled to below 175°F/80°C a third coat of the XTEND W-4008 can be hand applied for very difficult to release parts. Allow to dry to the touch, and then load the powder and mold. If spraying on, the mold should be allowed to cool to under 140°F/60°C. A full dry cycle is not always necessary.

PARTIAL DRY CYCLE FOR MODERATE PARTS:

For molders with (semi) independent arms, the arm can be moved in for a few minutes to heat through for a minimal cure (after two coats have been applied), and then brought back out to load the powder, close, and place back in the oven. **NO CURE**: XTEND W-4008 has also been proven to work on new molds and newly media blasted molds without any dry cycle. Once properly cleaned, simply apply two coats by hand and allow to dry to the touch between coats and after the second coat. The powder can then be loaded and molded. Although long term performance may be reduced, the XTEND W-4008 will provide excellent release even when no heat cure is completed.



Technical Data Sheet



Xtend W-4008

Mailing: Box 77 0855 Woodside, NY 11377 USA Shipping:58-20 Broadway, Woodside, NY 11377 USA Phone: 718-672-8300 ☐ Fax: 718-565-7447 E-mail: info @axelplast.com

www.axelplastics.com

Seasoned Tools with previous release agents:

For molds that are not stripped of previous mold release, one to two light coats can be applied to the mold and allowed to dry. It is not necessary to drycycle the mold if the mold/tool is seasoned with mold release. XTEND W-4008 will work right over the top of most other release agents. Just a light coat, when necessary, is all that is needed.

Touch-up coats can be applied as needed depending on part geometry, size, tooling, etc. No cure time is required for touch-up coats, however, the XTEND W-4008 should be dry to the touch.

NOTE: The XTEND W-4008 performs best when wiped on ambient or warm molds or sprayed (and then wiped in to the surface) on ambient molds (preferably below 140°F/60°C). Application on hot molds should be avoided, especially when spraying. The exception to this is when spraying with high quality spray equipment, such as: HVLP or similar equipment.

XTEND, MoldWiz, CleanWiz, and PasteWiz are registered trademarks of Axel Plastics Research Laboratories, Inc. This information is supplied for technically skilled professionals working at their own risk. AXEL believes the information to be accurate, although the Company assumes no liability in the validity of this information for any specific process or application. Moreover, AXEL will assume no liability from any direct and/or consequential damages of any kind that may arise from the use or non use of AXEL products or information supplied by the Company or its appointed representatives.

(Aug/3/2017)