



PLASTICS RESEARCH LABORATORIES, INC.
MOLD RELEASES & PROCESS ADDITIVES

50 Cambridge Drive, Monroe, CT 06468

Phone: 718-672-8300 • Fax: 718-565-7447
E-mail: info@axelplastics.com

www.axelplastics.com

Technical Data Sheet



W-7837D

Product Description

Proprietary resin emulsion comprising modified siloxane-based polymers which crosslink and form a release film upon evaporation of the water carrier.

Composition

Aqueous solution of proprietary resins and reactive surface modifiers.

Handling

Keep this water-based product from freezing and store below 100°F / 39°C.

Mix well before using.

Features

Easy, wipe-on
Matte Finish
No Odor
HAPs free
Cures quickly at ambient temperature

Uses

Ideal for open molding and other processes where uniform matte finish parts are required and a water-based release is desired. Ideal for wind blade production.

Molding polyester, vinyl ester & epoxy .

Typical Properties

pH	9.5 – 11.5
Color	Off White
Specific Gravity	1.005 @25°C
Viscosity	<15cps @25°C
Flash Point	Non Flammable
Shelf Life	12 months in original unopened package

Mold Preparation

New & Green FRP Molds:

Read AXEL publication FocusOn New & Green Molds.

Conditioned & Metal Molds:

Mold surfaces should be clean and free of previously used mold releases and other surface contaminants.

Mold Sealing

Applying WS-37 mold sealer prior to the application of the release may extend the productivity of the release coating.

Application Instructions

Hand Wiping:

1) Apply using a clean, woven, lint free cloth, such as the Scott Shop Towels On A Roll®, Kimberly-Clark WorkHorse® rags or WypAll® wipes, or even a good, heavy-duty plain white paper towel. Wet the cloth with release until it is damp but not dripping and wipe onto mold surface using smooth even strokes.

Spraying:

Many molders prefer to apply the semi-permanent release with a hand pump spray bottle. Using this method, a 2 – 3 square foot area can be misted and then lightly wiped with a clean cloth to distribute the release consistently across the surface.

2) After approximately 2 minutes, and before the release dries, lightly wipe over the surface with a clean cloth. Do not rub.

3) Wait approximately 15 minutes before applying the next coat of release. Allow this to dry and cure.

4) Allow a minimum of 15 additional minutes before molding. Allowing a longer time for the release to cure or heating the release coated mold will enhance release durability and performance.

5) A minimum of two coats of release are recommended for conditioned molds that have used a sealer prior to the release. If no sealer has been used, 4-6 coats of release should be applied.

XTEND, MoldWiz & PasteWiz are registered trademarks of Axel Plastics Research Laboratories.

This information is supplied for technically skilled professionals working at their own risk. AXEL believes the information to be accurate, although the Company assumes no liability in the validity of this information for any specific process or application. Moreover, AXEL will assume no liability from any direct and/or consequential damages of any kind that may arise from the use or non use of AXEL products or information supplied by the Company or its appointed representatives.

(080731)